


# SERVICE MOTOR KIT


## Low-Profile Tailgate & Poly Hopper Spreaders

### INSTALLATION INSTRUCTIONS

Use the appropriate mounting plate and mounting hole locations when installing the spreader service motor.



Use this plate and the mounting holes shown for all low-profile tailgate spreader installations.




Use this plate and the mounting holes shown for all poly hopper spreader installations.

# SERVICE MOTOR KIT


## Low-Profile Tailgate & Poly Hopper Spreaders

### INSTALLATION INSTRUCTIONS

Use the appropriate mounting plate when installing the spreader service motor.



Use this plate and the mounting holes shown for all low-profile tailgate spreader installations.



Use this plate and the mounting holes shown for all poly hopper spreader installations.

 **A DIVISION OR SUBSIDIARY OF DOUGLAS DYNAMICS, L.L.C.**

The company reserves the right under its product improvement policy to change construction or design details and furnish equipment when so altered without reference to illustrations or specifications used. This equipment manufacturer or the vehicle manufacturer may require or recommend optional equipment for spreaders. Do not exceed vehicle ratings with a spreader. The company offers a limited warranty for all spreaders and accessories. See separately printed page for this important information.

---

Lit. No. 68506, Rev. 00

**Printed in U.S.A.**

November 1, 2009

 **A DIVISION OR SUBSIDIARY OF DOUGLAS DYNAMICS, L.L.C.**

The company reserves the right under its product improvement policy to change construction or design details and furnish equipment when so altered without reference to illustrations or specifications used. This equipment manufacturer or the vehicle manufacturer may require or recommend optional equipment for spreaders. Do not exceed vehicle ratings with a spreader. The company offers a limited warranty for all spreaders and accessories. See separately printed page for this important information.

---

Lit. No. 68506, Rev. 00

**Printed in U.S.A.**

November 1, 2009